

**Flood Control Project Maintenance  
Levee Inspections**

**LMA District Cover Sheet**

**Spring 2012 Levee Inspection Results**

**Reclamation District No. 0765 Glide**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2012 Levee Inspection Results**

**Reclamation District No. 0765 Glide**

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	1.74
	Spring (March - May)	Summer (June - August)	(September - November) <b>Fall</b>	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/13/2012 - 3/13/2012			
DWR Inspector	Richard Willoughby			
Accompanied By	Dave Chestnut RD765			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance**  
**Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector
L/MR No.	Levee Mile		Category	Item	* Location Start	* Rating +	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Levee Mile	Start						Start	End	
1	Earthen Levee	Operations & Maintenance Manuals	WS	M Ma				°	°	44
								°	°	
										DWR ID: DWR_RD0765_01_s_2012_44
2	Earthen Levee	Emergency Supplies & Equipment	WS	A Ma				°	°	45
								°	°	
										DWR ID: DWR_RD0765_01_s_2012_45
3	Earthen Levee	Flood Preparedness & Training	WS	M Ma				°	°	46
								°	°	
										DWR ID: DWR_RD0765_01_s_2012_46
4	0.00 0.11 Earthen Levee	Encroachments	LS	M En	FE : Fences			38.502962 °	38.501373 °	12
								-121.560112 °	-121.560402 °	
										DWR ID: DWR_RD0765_01_s_2012_12
5	0.00 1.69 Earthen Levee	Vegetation	WS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.			38.502902 °	38.480728 °	6
								-121.559965 °	-121.549533 °	
										DWR ID: DWR_RD0765_01_s_2012_6
6	0.05 0.05 Earthen Levee	Trim / Thin Trees	LS	M Ma	T1 : Trim trees to at least five feet above ground level.			38.502253 °	38.502253 °	3
								-121.560192 °	-121.560192 °	
										DWR ID: DWR_RD0765_01_s_2012_3
7	0.09 0.09 Earthen Levee	Trim / Thin Trees	WS	M Ma	T1 : Trim trees to at least five feet above ground level.			38.501650 °	38.501650 °	27
								-121.560290 °	-121.560290 °	
										DWR ID: DWR_RD0765_01_s_2012_27
8	0.12 0.19 Earthen Levee	Trim / Thin Trees	LS	M Ma	T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.			38.501215 °	38.500271 °	28
								-121.560432 °	-121.560434 °	Y
										DWR ID: DWR_RD0765_01_s_2012_28
9	0.14 0.14 Earthen Levee	Vegetation	LS	M Ma	V4 : Elderberries are blocking visibility and flood fight capability.			38.500928 °	38.500928 °	22
								-121.560431 °	-121.560431 °	
										DWR ID: DWR_RD0765_01_s_2012_22
10	0.19 0.35 Earthen Levee	Trim / Thin Trees	LS	M Ma	T1 : Trim trees to at least five feet above ground level.			38.500343 °	38.498032 °	14
								-121.560507 °	-121.560337 °	
										DWR ID: DWR_RD0765_01_s_2012_14
11	0.21 0.21 Earthen Levee	Trim / Thin Trees	WS	M Ma	T1 : Trim trees to at least five feet above ground level.			38.500018 °	38.500018 °	25
								-121.560457 °	-121.560457 °	
										DWR ID: DWR_RD0765_01_s_2012_25
12	0.25 0.28 Earthen Levee	Trim / Thin Trees	WS	U Ma	T2 : Thin trees to allow visibility of the ground and room to flood fight.			38.499405 °	38.499042 °	11
								-121.560445 °	-121.560430 °	Y
										DWR ID: DWR_RD0765_01_s_2012_11
13	0.32 0.32 Earthen Levee	Trim / Thin Trees	WS	M Ma	T1 : Trim trees to at least five feet above ground level.			38.498453 °	38.498453 °	23
								-121.560360 °	-121.560360 °	
										DWR ID: DWR_RD0765_01_s_2012_23
14	0.41 0.41 Earthen Levee	Trim / Thin Trees	LS	M Ma	T1 : Trim trees to at least five feet above ground level.			38.497196 °	38.497196 °	21
								-121.560147 °	-121.560147 °	
										DWR ID: DWR_RD0765_01_s_2012_21

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance**  
**Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Sacramento River							Right	1.74	03/13/2012 03/13/2012	Richard Willoughby	
L/MR No	Levee Mile		Category	Item	* Location	* Rating	Action/Comment			GPS Latitude/Longitude	Issue No.
	Start	End								Start	End
15	0.41	0.52	Earthen Levee	Trim / Thin Trees	WS Ma	M	T1 : Trim trees to at least five feet above ground level.		38.497125 ° 38.495648 ° 24 -121.560087 ° -121.559391 ° DWR ID: DWR_RD0765_01_s_2012_24		
16	0.43	0.47	Earthen Levee	Trim / Thin Trees	LS Ma	M	T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.		38.496792 ° 38.496321 ° 32 -121.560026 ° -121.559842 ° Y DWR ID: DWR_RD0765_01_s_2012_32		
17	0.48	0.50	Earthen Levee	Vegetation	LS Ma	U	V2 : Remove the wild growth other than native grasses from the levee slopes.		38.496217 ° 38.495855 ° 33 -121.559788 ° -121.559586 ° Y DWR ID: DWR_RD0765_01_s_2012_33		
18	0.54	0.54	Earthen Levee	Trim / Thin Trees	LS Ma	M	T1 : Trim trees to at least five feet above ground level.		38.495347 ° 38.495347 ° 34 -121.559291 ° -121.559291 ° DWR ID: DWR_RD0765_01_s_2012_34		
19	0.57	0.60	Earthen Levee	Trim / Thin Trees	WS Ma	M	T1 : Trim trees to at least five feet above ground level.		38.495035 ° 38.494642 ° 10 -121.559027 ° -121.558697 ° DWR ID: DWR_RD0765_01_s_2012_10		
20	0.62	0.65	Earthen Levee	Trim / Thin Trees	LS Ma	M	T1 : Trim trees to at least five feet above ground level.		38.494468 ° 38.494037 ° 16 -121.558577 ° -121.558192 ° DWR ID: DWR_RD0765_01_s_2012_16		
21	0.65	0.65	Earthen Levee	Trim / Thin Trees	WS Ma	M	T1 : Trim trees to at least five feet above ground level.		38.494097 ° 38.494097 ° 19 -121.558192 ° -121.558192 ° DWR ID: DWR_RD0765_01_s_2012_19		
22	0.66	0.66	Earthen Levee	Trim / Thin Trees	WS Ma	M	T1 : Trim trees to at least five feet above ground level.		38.493917 ° 38.493917 ° 18 -121.558041 ° -121.558041 ° DWR ID: DWR_RD0765_01_s_2012_18		
23	0.69	0.69	Earthen Levee	Trim / Thin Trees	LS Ma	M	T1 : Trim trees to at least five feet above ground level.		38.493596 ° 38.493596 ° 35 -121.557832 ° -121.557832 ° DWR ID: DWR_RD0765_01_s_2012_35		
24	0.71	0.71	Earthen Levee	Trim / Thin Trees	WS Ma	M	T1 : Trim trees to at least five feet above ground level.		38.493392 ° 38.493392 ° 15 -121.557640 ° -121.557640 ° DWR ID: DWR_RD0765_01_s_2012_15		
25	0.78	0.81	Earthen Levee	Trim / Thin Trees	LS Ma	M	T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.		38.492392 ° 38.492034 ° 36 -121.557026 ° -121.556820 ° DWR ID: DWR_RD0765_01_s_2012_36		
26	0.87	1.03	Earthen Levee	Trim / Thin Trees	LS Ma	U	T1 : Trim trees to at least five feet above ground level.		38.491283 ° 38.489149 ° 17 -121.556360 ° -121.555121 ° Y DWR ID: DWR_RD0765_01_s_2012_17		
27	0.97	0.97	Earthen Levee	Vegetation	LS Ma	U	V2 : Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Dense berryvines on landside slope.		38.489962 ° 38.489962 ° 81 -121.555573 ° -121.555573 ° Y DWR ID: DWR_RD0765_01_s_2012_81		
28	0.99	1.05	Earthen Levee	Trim / Thin Trees	WS Ma	M	T2 : Thin trees to allow visibility of the ground and room to flood fight.		38.489705 ° 38.488990 ° 8 -121.555385 ° -121.554993 ° Y DWR ID: DWR_RD0765_01_s_2012_8		
29	1.02	1.02	Earthen Levee	Vegetation	LS Ma	U	V7 : Trees / Woody Vegetation		38.489283 ° 38.489283 ° 40 -121.555223 ° -121.555223 ° Y DWR ID: DWR_RD0765_01_s_2012_40		

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating	A : Acceptable	N : Not Inspected/Rated	+ Issue Type
	M : Minimally Acceptable	C : Corrected	Ma : Maintenance Deficiency
	U : Unacceptable	A/W : Acceptable but Monitor & Maintain	Ob : Design & System Obsolescence
			En : Enforcement

**Flood Control Project Maintenance**  
**Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector	
MR No	Levee Mile		Category	Item	* Location +	* Rating +	Action/Comment			GPS Latitude/Longitude	Issue No.
	Start	End					Start	End	Photo		
30	1.08	1.08	Earthen Levee	Trim / Thin Trees	LS Ma	U	T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.	38.488503 ° -121.554757 °	38.488503 ° -121.554757 °	37	Y
										DWR ID: DWR_RD0765_01_s_2012_37	
31	1.10	1.16	Earthen Levee	Trim / Thin Trees	LS Ma	M	T1 : Trim trees to at least five feet above ground level.	38.488279 ° -121.554615 °	38.487465 ° -121.554117 °	38	
										DWR ID: DWR_RD0765_01_s_2012_38	
32	1.15	1.15	Earthen Levee	Vegetation	LS Ma	M	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.487653 ° -121.554248 °	38.487653 ° -121.554248 °	39	Y
										DWR ID: DWR_RD0765_01_s_2012_39	
33	1.16	1.16	Earthen Levee	Trim / Thin Trees	WS Ma	M	T1 : Trim trees to at least five feet above ground level.	38.487473 ° -121.554080 °	38.487473 ° -121.554080 °	9	
										DWR ID: DWR_RD0765_01_s_2012_9	
34	1.19	1.22	Earthen Levee	Encroachments	LS En	M	BU : Buildings	38.487127 ° -121.553910 °	38.486702 ° -121.553652 °	43	
										DWR ID: DWR_RD0765_01_s_2012_43	
35	1.32	1.35	Earthen Levee	Trim / Thin Trees	LS Ma	M	T1 : Trim trees to at least five feet above ground level.	38.485280 ° -121.552860 °	38.485002 ° -121.552687 °	26	
										DWR ID: DWR_RD0765_01_s_2012_26	
36	1.33	1.33	Earthen Levee	Encroachments	WS En	M	TR : Tree or limb Inspector Comments: Down tree on waterside slope.	38.485245 ° -121.552807 °	38.485245 ° -121.552807 °	20	
										DWR ID: DWR_RD0765_01_s_2012_20	
37	1.36	1.36	Earthen Levee	Trim / Thin Trees	WS Ma	U	T1 : Trim trees to at least five feet above ground level.	38.484877 ° -121.552540 °	38.484877 ° -121.552540 °	7	
										DWR ID: DWR_RD0765_01_s_2012_7	
38	1.41	1.41	Earthen Levee	Trim / Thin Trees	WS Ma	M	T1 : Trim trees to at least five feet above ground level.	38.484316 ° -121.552115 °	38.484316 ° -121.552115 °	4	
										DWR ID: DWR_RD0765_01_s_2012_4	
39	1.44	1.47	Earthen Levee	Trim / Thin Trees	WS Ma	M	T2 : Thin trees to allow visibility of the ground and room to flood fight.	38.483925 ° -121.551845 °	38.483530 ° -121.551587 °	5	
										DWR ID: DWR_RD0765_01_s_2012_5	
40	1.46	1.46	Earthen Levee	Trim / Thin Trees	LS Ma	M	T1 : Trim trees to at least five feet above ground level.	38.483640 ° -121.551727 °	38.483640 ° -121.551727 °	41	
										DWR ID: DWR_RD0765_01_s_2012_41	
41	1.50	1.51	Earthen Levee	Trim / Thin Trees	LS Ma	M	T1 : Trim trees to at least five feet above ground level.	38.483170 ° -121.551367 °	38.482965 ° -121.551265 °	42	
										DWR ID: DWR_RD0765_01_s_2012_42	
42	1.54	1.63	Earthen Levee	Vegetation	LS Ma	U	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.482590 ° -121.551020 °	38.481420 ° -121.550262 °	29	
										DWR ID: DWR_RD0765_01_s_2012_29	
43	1.60	1.67	Earthen Levee	Trim / Thin Trees	WS Ma	M	T1 : Trim trees to at least five feet above ground level.	38.480913 ° -121.549677 °	38.480993 ° -121.549738 °	2	
										DWR ID: DWR_RD0765_01_s_2012_2	
44	1.60	1.60	Earthen Levee	Vegetation	WS Ma	M	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.481841 ° -121.550438 °	38.482028 ° -121.550512 °	31	
										DWR ID: DWR_RD0765_01_s_2012_31	

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector	
LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment			GPS Latitude/Longitude	Issue No.
	Start	End								Start	End
45	1.69	1.69	Earthen Levee	Encroachments	WSA/W	GA : Garbage En	Inspector Comments: District removed trash.			38.480770 °	38.480895 °
										-121.549514 °	-121.549556 °
										Y	DWR ID: DWR_RD0765_01_s_2012_30
46	1.70	1.70	Earthen Levee	Encroachments	WSA/W	PR : Prunings Ma	Inspector Comments: Landowner burned pruning pile.			38.480632 °	38.480632 °
										-121.549543 °	-121.549543 °
										Y	DWR ID: DWR_RD0765_01_s_2012_13
47	1.70	1.73	Earthen Levee	Trim / Thin Trees	WS	U	T1 : Trim trees to at least five feet above ground level.			38.480602 °	38.480257 °
						Ma				-121.549523 °	-121.549458 °
										Y	DWR ID: DWR_RD0765_01_s_2012_1

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	8
Start Levee Mile	0.12
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking west at trees on landside toe.	
<a href="#">richard_s_20120313_963.jpg</a>	



Levee Mile Report Line	8
Start Levee Mile	0.12
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (south) at trees on landside slope & toe.	
<a href="#">richard_s_20120313_964.jpg</a>	



Levee Mile Report Line	12
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking northeast at overgrown trees on waterside slope.	
<a href="#">richard_s_20120313_956.jpg</a>	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable

N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	12
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking north at dense trees on waterside slope from fall 2010 inspection.	
richard_s_20120313_957.jpg	



Levee Mile Report Line	12
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense vegetation and trees from 2011 spring inspection.	
richard_s_20120313_958.jpg	



Levee Mile Report Line	16
Start Levee Mile	0.43
End Levee Mile	0.47
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking southwest at dense vegetation on landside slope and toe.	
richard_s_20120319_162.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance**  
**Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	17
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking northwest at trees on landside toe from 2010 fall inspection.	
richard_s_20120313_971.jpg	



Levee Mile Report Line	17
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking downstream (south) at trees on landside slope & toe.	
richard_s_20120313_972.jpg	



Levee Mile Report Line	17
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking downstream (southwest) at dense vegetation on landside slope.	
richard_s_20120313_973.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance**  
**Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**


**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	17
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking upstream (northwest) at dense vegetation on landside slope.	
richard_s_20120313_974.jpg	



Levee Mile Report Line	26
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (south) at dense trees on landside slope and toe.	
richard_s_20120313_960.jpg	



Levee Mile Report Line	26
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense trees on landside slope and toe.	
richard_s_20120313_961.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	26
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking south at dense trees on landside shoulder and slope. (November 2011)	
richard_s_20120313_962.jpg	



Levee Mile Report Line	26
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking southwest at dense trees on landside slope and toe spring 2012	
richard_s_20120319_163.jpg	



Levee Mile Report Line	27
Start Levee Mile	0.97
End Levee Mile	0.97
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking west at dense berryvines and wildroses on landside shoulder and slope. (November 2011)	
richard_s_20120313_980.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	27
Start Levee Mile	0.97
End Levee Mile	0.97
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking northwest at vines on landside toe spring 2012

richard\_s\_20120319\_164.jpg



Levee Mile Report Line	28
Start Levee Mile	0.99
End Levee Mile	1.05
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (northeast) at dense vegetation on waterside slope.

richard\_s\_20120313\_954.jpg



Levee Mile Report Line	28
Start Levee Mile	0.99
End Levee Mile	1.05
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (north) dense vegetation and trees on waterside shoulder and slope.

richard\_s\_20120313\_955.jpg



<b>* Location</b>
LS : Land Side
WS : Water Side
CR : Crown

<b>** Rating</b>
A : Acceptable
M : Minimally Acceptable
U : Unacceptable

N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

<b>+ Issue Type</b>
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance**  
**Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	28
Start Levee Mile	0.99
End Levee Mile	1.05
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking south at dense trees and vegetation	
richard_s_20120319_161.jpg	



Levee Mile Report Line	29
Start Levee Mile	1.02
End Levee Mile	1.02
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking southwest at fig trees and other trees on landside slope and toe.	
richard_s_20120319_165.jpg	



Levee Mile Report Line	30
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (south) at trees on landside slope & toe from 2010 fall inspection.	
richard_s_20120313_975.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance**  
**Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	30
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking west at trees on landside slope & toe.	
richard_s_20120313_976.jpg	



Levee Mile Report Line	30
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (southwest) at dense trees on landside slope and toe.	
richard_s_20120313_977.jpg	



Levee Mile Report Line	32
Start Levee Mile	1.15
End Levee Mile	1.15
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking downstream (southwest) at wild roses on landside slope & toe.	
richard_s_20120313_978.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance**  
**Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	34
Start Levee Mile	1.19
End Levee Mile	1.22
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Looking northwest at buildings along landside toe.	
<a href="#">richard_s_20120313_979.jpg</a>	



Levee Mile Report Line	36
Start Levee Mile	1.33
End Levee Mile	1.33
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Looking northeast at tree limbs on waterside slope.	
<a href="#">richard_s_20120319_160.jpg</a>	



Levee Mile Report Line	37
Start Levee Mile	1.36
End Levee Mile	1.36
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense vegetation on waterside slope.	
<a href="#">richard_s_20120313_953.jpg</a>	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	39
Start Levee Mile	1.44
End Levee Mile	1.47
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense trees on waterside slope.	
richard_s_20120313_952.jpg	



Levee Mile Report Line	42
Start Levee Mile	1.54
End Levee Mile	1.63
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking downstream (southwest) at trees, vines & wildroses on landside slope & toe from 2010 fall inspection	
richard_s_20120313_965.jpg	



Levee Mile Report Line	42
Start Levee Mile	1.54
End Levee Mile	1.63
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking downstream (south) at trees, vines & wildroses on landside slope & toe.	
richard_s_20120313_966.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable

N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	42
Start Levee Mile	1.54
End Levee Mile	1.63
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking downstream (south) at dense vegetation on landside slope and toe.	
richard_s_20120313_967.jpg	



Levee Mile Report Line	42
Start Levee Mile	1.54
End Levee Mile	1.63
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking south at dense vegetation on landside shoulder and slope. (November 2011)	
richard_s_20120313_968.jpg	



Levee Mile Report Line	42
Start Levee Mile	1.54
End Levee Mile	1.63
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking south at dense vegetation on landside slope and toe spring 2012.	
richard_s_20120319_166.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	43
Start Levee Mile	1.60
End Levee Mile	1.67
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking south at dense trees on waterside slope.	
richard_s_20120313_950.jpg	



Levee Mile Report Line	43
Start Levee Mile	1.60
End Levee Mile	1.67
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking east at dense vegetation on waterside slope.	
richard_s_20120313_951.jpg	



Levee Mile Report Line	45
Start Levee Mile	1.69
End Levee Mile	1.69
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Looking northeast at garbage on waterside slope. (May 2011)	
richard_s_20120313_969.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	45
Start Levee Mile	1.69
End Levee Mile	1.69
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Looking north at garbage and pruning pile on waterside shoulder. (November 2011)	
richard_s_20120313_970.jpg	



Levee Mile Report Line	46
Start Levee Mile	1.70
End Levee Mile	1.70
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Looking southeast at pruning piles on waterside shoulder & slope.	
richard_s_20120313_959.jpg	



Levee Mile Report Line	47
Start Levee Mile	1.70
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at trees on waterside slope.	
richard_s_20120313_947.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2012**

**Reclamation District No. 0765 Glide**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	03/13/2012 03/13/2012	Richard Willoughby

Levee Mile Report Line	47
Start Levee Mile	1.70
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking east at trees on waterside slope.	
richard_s_20120313_948.jpg	



Levee Mile Report Line	47
Start Levee Mile	1.70
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking south at dense trees and vegetation on waterside slope. (November 2011)	
richard_s_20120313_949.jpg	



* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement